UNIFIED TRIPLE MONITOR MOUNT

INSTRUCTION MANUAL



REQUIRED TOOLS:



1



Profile 4040 L=220

2x



Profile 4040 L=950

1x



Profile 4040 L=500

2x



Bracket

4x



Corner Cover 4040

4x



Cover 4040

8x



Bracket

2x



Corner 4040

4x

M8x20 (Black)

10x

M8x16

24x

(16x Black)



M4x12

12x



Spacer M4x10

12x



Click-in Nut M8

34x



Plain Washer M8

14x

STANDARD VESA KIT:



VESA Bracket

3x



Click-in Nut M6

6x

Plain Washer M6

6x



M6x16

6x

EASY ALIGNMENT KIT:

(separate manual)



3x

---

2 ⚠ Left profile 4040 L=500



Place these M6 only for the **STANDARD VESA** plates

3

Right profile 4040 L=500



Place these M6 only for the **STANDARD VESA** plates

4



Place these M6 only for the **STANDARD VESA** plates

5

Mount both brackets to the upright profiles of your rig, using the black M8x20 bolts and the M8 washers.



6



7



8



9

VESA bracket can be mounted up- or downwards. For screens > 27” we recommend mounting it upwards.

If you own a Unified Triple with the **EASY MONITOR ALIGNMENT KIT**, please see skip this step and see that manual for detailed mounting instructions.



10

Place all the cover caps.



11 ⚠ If necessary, use M4x10 spacers (included in package)



(12x)